Roll	No.							Total No. o	f Pages :	03

Total No. of Questions: 09

B.Tech.(ME) (2018 Batch) (Sem.-3) MACHINE DRAWING

Subject Code: BTME-303-18 M.Code: 76419

Time: 3 Hrs. Max. Marks: 60

INSTRUCTIONS TO CANDIDATES:

- There are three sections in this question paper. Attempt ALL the questions from SECTION-A.
- 2. Attempt any TWO questions from SECTION-B and any ONE question from SECTION-C.
- 3. First angle projection to be used. You may assume any missing dimension.

SECTION-A

Q1. Write briefly:

a)	Explain clearance fit, transition fit and interference fit.	2
b)	Draw a machining symbol to represent a surface roughness (R_a) value of 1.5 μm to obtained by using milling process for machining?	be 2
c)	How internal threads are shown in sections? Explain with drawings.	2
d)	What is function of clearance in cotter joint?	2
e)	What is a lock nut? Where is it used?	2
f)	What is expansion joint?	2
g)	What is application and function of a feed check valve?	2
h)	What is a T-Bolt and where is it used?	2
i)	What is a revolved section? Explain with the help of a drawing.	2
i)	What is application of foot step bearing?	2

1 M-76419 (S2)- 1504

SECTION-B (FREEHAND SKETCHING)

- Q2. Draw freehand sketch of top half sectioned front view of pin type flexible coupling. 5
- Q3. Draw freehand sketches of front view and top view of a cotter joint.
- Q4. Draw a freehand sketch of flanged pipe joint. 5

SECTION-C

- Q5. Assemble the parts of **Connecting rod** given in Fig.1 and draw the following views (with bill of materials):
 - a) Elevation
 - b) Top view (full section)

30




Fig. 1

2 | M-76419 (S2)- 1504

- Q6. Assemble the parts of a **Plummer block** given in Fig.2 and draw the following views (with bill of materials):
 - a) Elevation left half in section

b) Plan 30




Fig. 2

NOTE: Disclosure of Identity by writing Mobile No. or Making of passing request on any page of Answer Sheet will lead to UMC against the Student.

3 M-76419 (S2)- 1504